

DEMAGNETIZATION
AT 20 A/cm (%)

FIG 2 DEMAGNETIZATION DEPENDENT
ON COERCIVITY H_C




FIG 3 TENSILE STRESS SENSITIVITY
OF REMANENCE B_r




FIG 4 RELATIVE CHANGE IN FLUX
FOR BENDING AT RADIUS r

